



Electrical Specifications

Ranges and Resolution

abs: absolute reference (atmospheric pressure to zero at full vacuum)
 vac: vacuum gauge, minus sign not used unless specified
 Resolution is fixed as indicated in table below
 Contact factory for engineering units not listed

Contact factory for other engineering units	120.0 inHg	1600 mmHg	35.0 bar	1.000 kg/cm ² abs
	199.9 inHg abs	760 torr abs	70.0 bar	1.000 kg/cm ² vac
	199.9 inHg	1600 torr abs	140.0 bar	±1.000 kg/cm ²
3.00 psig	50.0 oz/in ²	2100 mmH ₂ O	199.9 bar	1.000 kg/cm ²
5.00 psig	80.0 oz/in ²	3500 mmH ₂ O	350 bar	1.999 kg/cm ² abs
15.00 psi abs	240 oz/in ² abs	199.9 cmH ₂ O	19.99 kPa	1.999 kg/cm ²
15.00 psig vac	240 oz/in ² vac	350 cmH ₂ O	35.0 kPa	4.00 kg/cm ²
±15.0 psig	±240 oz/in ²	1000 cmH ₂ O	100.0 kPa abs	7.00 kg/cm ² abs
15.00 psig	240 oz/in ²	2100 cmH ₂ O	100.0 kPa vac	7.00 kg/cm ²
30.0 psi abs	85.0 inH ₂ O	199.9 mbar	±100.0 kPa	14.00 kg/cm ²
30.0 psig	140.0 inH ₂ O	350 mbar	100.0 kPa	19.99 kg/cm ²
60.0 psig	400 inH ₂ O abs	1000 mbar abs	199.9 kPa abs	35.0 kg/cm ²
100.0 psi abs	400 inH ₂ O vac	1000 mbar vac	199.9 kPa	70.0 kg/cm ²
100.0 psig	±400 inH ₂ O	±1000 mbar	400 kPa	140.0 kg/cm ²
199.9 psig	400 inH ₂ O	1000 mbar	700 kPa abs	199.9 kg/cm ²
300 psig	850 inH ₂ O	1999 mbar abs	700 kPa	350 kg/cm ²
500 psig	7.00 ftH ₂ O	1999 mbar	1500 kPa	1.000 atm abs
1000 psig	12.00 ftH ₂ O	4000 mbar	1999 kPa	±1.000 atm
1999 psig	35.0 ftH ₂ O	1.000 bar abs	3500 kPa	1.000 atm
3000 psig	70.0 ftH ₂ O	1.000 bar vac	5000 kPa	4.00 atm
5000 psig	140.0 ftH ₂ O	±1.000 bar	3.50 MPa	7.00 atm
6.00 inHg	230 ftH ₂ O	1.000 bar	7.00 MPa	14.00 atm
10.00 inHg	480 ftH ₂ O	1.999 bar abs	14.00 MPa	19.99 atm
30.0 inHg abs	150.0 mmHg	1.999 bar	19.99 MPa	35.0 atm
30.0 inHg vac	260 mmHg	4.00 bar	35.0 MPa	70.0 atm
±30.0 inHg	760 mmHg abs	7.00 bar abs	1000 g/cm ² abs	135.0 atm
30.0 inHg	760 mmHg vac	7.00 bar	1000 g/cm ²	199.9 atm
60.0 inHg abs	760 mmHg	14.00 bar	2100 g/cm ² abs	340 atm
60.0 inHg	1600 mmHg abs	19.99 bar	2100 g/cm ²	3-15 psig

Accuracy (linearity, hysteresis, repeatability)

Standard: ±0.25% of full scale ±1 least significant digit
 Optional: **-HA** ±0.1% FS ±1LSD (most ranges)
CD Factory calibration data
NC NIST traceable test report and calibration data

Display

3 readings per second nominal display update rate
 Ranges up to 1999: 3½ digit LCD, ½" digit height
 3000 and 5000 psi ranges: 4 digit LCD, 0.4" digit height

Controls

Non-interactive zero and span, ±10% range
 Test calibration level: 0-100% range
 Retransmission zero and span: Internal potentiometers

Loop Supply Voltage

Any DC supply/loop resistance that maintains 8 to 32 VDC at gauge terminals
 Gauge is reverse polarity protected
 3 ft long, 2-conductor 22 AWG cable
 Order optional **9046-24-008** loop power supply

Low Loop Indication

Below approximately 7.8 VDC
 Ranges up to 1999: None
 3000 and 5000 psi ranges: All decimal points flash

Output Characteristics

True analog output, 50 millisecond typical response time
 If gauge terminal voltage falls below approx. 7.8 VDC erratic operation may occur

Test Function

Front panel TEST button, when depressed sets loop current and display to test calibration level, independent of pressure input, to allow testing of system operation.
 Test Cal level is set by multiturn potentiometer to any value from 0 to 100% of FSO.

Environmental

Storage Temperature -40 to 203°F (-40 to 95°C)
 Operating Temperature -4 to 185°F (-20 to 85°C)
 Compensated Temperature 32 to 158°F (0 to 70°C)

- ±0.25% Test Gauge Accuracy
- 316 Stainless Steel Wetted Parts
- Pressure, Vacuum, or Absolute
- Analog 4-20 mA Output
- Output Test Function

DPG1000L30INHGA
30.0 inHg Absolute



DPG1000L5000PSIG
5000 psig range

Mechanical Specifications

Size

3.38" W x 2.88" H x 1.65" D housing
 Add approximately 0.75" to height for pressure fitting
 Add approximately 1" to depth for strain relief and wire clearance

Weight

Gauge: 9 ounces (approx)
 Shipping weight: 1 pound (approx)

Material

Extruded aluminum case, epoxy powder coated
 Polycarbonate cover. Front and rear gaskets

Color

Light gray body, light gray/blue front

Pressure/Vacuum Connection and Material

¼" NPT male, 316 stainless steel

Media Compatibility

All wetted parts are 316 SS
 Compatible with most liquids and gases

Overpressure

3000 psig range and metric equivalents: 5000 psig
 5000 psig range and metric equivalents: 7500 psig
 All others 2x rated pressure minimum

Burst Pressure

4x rated pressure minimum or 10,000 psi, whichever is less



cecomp.com

1220 American Way Libertyville, IL 60048
 Phone: 800-942-0315 Fax: 800-949-7502

api-usa.com



DESCRIPTION

All operating power for the **DPG1000L** gauge is supplied by the 4-20 mA current loop. The 2-wire connection allows the **DPG1000L** to be used as a digital indicating transmitter in any 4-20 mA current loop application. The output is a continuous analog signal based on the transducer output rather than the display. The output is filtered to improve noise immunity and has a response time of about 50 msec. The temperature compensated piezoresistive transducer features 316 stainless steel wetted parts.

The **TEST** pushbutton, when depressed, switches the display and output loop to a preset level determined by the setting of a Test potentiometer.

INSTALLATION AND PRECAUTIONS

Install or remove gauge using wrench on hex fitting only. Do not attempt to tighten by turning housing or any other part of the gauge. Use fittings appropriate for the pressure range of the gauge. Do not apply vacuum to gauges not designed for vacuum operation. Due to the hardness of 316 stainless steel, it is recommended that a thread sealant be used to ensure leak-free operation.

NEVER insert objects into the gauge port or blow out with compressed air. Permanent damage not covered by warranty will result to the sensor.

ELECTRICAL CONNECTION

Connection to the **DPG1000L** is made with the 2-wire cable at the gauge rear. Connect the loop (+) supply to the RED lead and the loop (-) supply to the BLACK lead. Reversing the connections will not harm the gauge but the **DPG1000L** will not operate with incorrect polarity.


LOOP VOLTAGE

Select a loop power supply voltage and total loop resistance so that when the loop current is 20 mA, the gauge will have at least 8 VDC at its terminals. For correct operation and to avoid erratic or erroneous readings, the gauge terminal voltage must not fall below 8 VDC. Too large a loop resistance will cause the gauge output to "limit" or saturate before reaching its full 20 mA output.

The **minimum** loop supply voltage may be calculated from the formula:

$$V_{min} = 8V + (20mA \times \text{Total loop resistance})$$

If the terminal voltage of the gauge falls below about 7.8 VDC, erratic operation may occur. This is an indication that the loop supply/resistance may not allow adequate headroom for reliable operation. This should never occur in normal use. If it does, examine the loop supply/resistance.



OPERATION

The **DPG1000L** is designed for continuous operation. Warm-up time is negligible. The display will show the system pressure or vacuum, and the loop current also will be proportional to the system pressure/vacuum;

4 mA = Zero or low end
20 mA = Span, full-scale or high end.

TEST BUTTON

When the front-panel **TEST** button is held depressed, the display and loop current are switched, independent of the system pressure, to a test level determined by the setting of the Test potentiometer. This test mode will allow setup and testing of the current loop by switching to this test level whenever desired without having to alter the system pressure.

To set the test output level, see gauge label for location of Test potentiometer. Press and hold the front-panel **TEST** button and adjust the Test potentiometer to set the display and loop current to the desired test level.

www.cecemp.com

Cecomp maintains a constant effort to upgrade and improve its products. Specifications are subject to change without notice. Consult factory for your specific requirements.

CALIBRATION

See gauge label for location of individual controls to adjust the zero and span of the display.



Gauge Reference – Units may be re-zeroed without affecting the span calibration. The gauge port must be open to the ambient with no pressure or vacuum applied. Adjust the Zero control until the gauge reads zero with the minus (-) sign occasionally flashing.

Span calibration should only be attempted if the user has access to a pressure reference of known accuracy. The quality of the calibration is only as good as the accuracy of the calibration equipment and ideally should be at least four times the gauge accuracy. Zero calibration must be done before span calibration. Record readings at three to five points over the range of gauge and adjust span control to minimize error and meet specifications.

Absolute Reference – Gauges require vacuum generation and atmospheric pressure measurement equipment for accurate calibration and thus are more difficult to calibrate in the field. Gauges may be returned to Cecomp Electronics for factory certified recalibration. NIST traceability is available.

The **DPG1000L** has internal controls to adjust the agreement between the displayed value and the 4-20 mA loop current. These are set at the factory and should not normally be adjusted. If adjustment is necessary, consult factory. Accurate pressure generation and measurement and current measurement equipment are required to successfully complete this calibration.

DIMENSIONS



PART NUMBERS

DPG1000L range units ref
Pressure/Vacuum Range (see table) →
Units (see table) →
G=Gauge, A=Absolute, VAC=Vacuum

Example: **DPG1000L15PSIA** = DPG1000, Loop powered, 15.00 PSI Absolute

Unit Abbreviations			
psi = PSI	ftH ₂ O = FTH ₂ O	kg/cm ² = KGCM	mbar = MBAR
inHg = INHG	mmHg = MMHG	g/cm ² = GCM	bar = BAR
oz/in ² = ZIN	torr = TORR	KPa = KPA	cmH ₂ O = CMH ₂ O
inH ₂ O = INH ₂ O	mmH ₂ O = MMH ₂ O	MPa = MPA	atm = ATM